



**1<sup>ST</sup> EDITION**

**CGA E-19 — 2018**

**REAFFIRMED 2024**

**GUIDELINE FOR  
SAFE USE OF  
OXY-FUEL  
EQUIPMENT USED  
IN WELDING,  
CUTTING, AND  
ALLIED PROCESSES**

---



**PLEASE NOTE:**

The information contained in this document was obtained from sources believed to be reliable and is based on technical information and experience currently available from members of the Compressed Gas Association, Inc. and others. However, the Association or its members, jointly or severally, make no guarantee of the results and assume no liability or responsibility in connection with the information or suggestions herein contained. Moreover, it should not be assumed that every acceptable commodity grade, test or safety procedure or method, precaution, equipment or device is contained within, or that abnormal or unusual circumstances may not warrant or suggest further requirements or additional procedure.

This document is subject to periodic review, and users are cautioned to obtain the latest edition. The Association invites comments and suggestions for consideration. In connection with such review, any such comments or suggestions will be fully reviewed by the Association after giving the party, upon request, a reasonable opportunity to be heard. Proposed changes may be submitted via the Internet at our web site, [www.cganet.com](http://www.cganet.com).

This document should not be confused with federal, state, provincial, or municipal specifications or regulations; insurance requirements; or national safety codes. While the Association recommends reference to or use of this document by government agencies and others, this document is purely voluntary and not binding unless adopted by reference in regulations.

A listing of all publications, audiovisual programs, safety and technical bulletins, and safety posters is available via the Internet at our website at [www.cganet.com](http://www.cganet.com). For more information contact CGA at Phone: 703-788-2700, ext. 799. E-mail: [customerservice@cganet.com](mailto:customerservice@cganet.com).

Work Item 23-047  
Industrial Gases Apparatus Committee

NOTE—No technical information has been changed from the 2018 edition. This reaffirmed edition may include minor editorial changes.

REAFFIRMED: 2024  
FIRST EDITION: 2018

© 2018 The Compressed Gas Association, Inc. All rights reserved.

All materials contained in this work are protected by United States and international copyright laws. No part of this work may be reproduced or transmitted in any form or by any means, electronic or mechanical including photocopying, recording, or any information storage and retrieval system without permission in writing from The Compressed Gas Association, Inc. All requests for permission to reproduce material from this work should be directed to The Compressed Gas Association, Inc., 8484 Westpark Drive, Suite 220, McLean, VA 22102. You may not alter or remove any trademark, copyright or other notice from this work.

<b>Contents</b>	<b>Page</b>
1 Introduction.....	1
2 Scope .....	1
3 Definitions.....	1
4 Safe use of oxy-fuel gas welding and cutting apparatus .....	1
4.1 DOs for use of oxy-fuel gas welding and cutting apparatus .....	1
4.2 DO NOTs for use of oxy-fuel gas welding and cutting apparatus.....	3
5 Safe use of high flow oxy-fuel gas and air-fuel gas heating torch apparatus .....	4
5.1 DOs for use of high flow oxy-fuel gas and air-fuel gas heating torch apparatus .....	4
5.2 DO NOT's for use of high flow oxy-fuel gas and air-fuel gas heating torch apparatus.....	5
6 References .....	6
7 Additional references.....	6

## 1 Introduction

Oxy-fuel welding and cutting apparatus and heating torch apparatus can be used safely. However, failure to take safety precautions can result in property damage, personal injury, and/or the possible loss of life.

## 2 Scope

This guideline provides safety precautions for the use of oxy-fuel gas welding and cutting apparatus and oxy-fuel and air-fuel gas heating torch apparatus. Failure to take basic safety precautions can result in property damage, personal injury, and/or possible loss of life.

This publication does not include specific procedures, nor shall it be viewed as working instructions.

## 3 Definitions

For the purpose of this publication, the following definitions apply.

### 3.1 Publication terminology

#### 3.1.1 Shall

Indicates that the procedure is mandatory. It is used wherever the criterion for conformance to specific recommendations allows no deviation.

#### 3.1.2 Should

Indicates that a procedure is recommended.

#### 3.1.3 May

Indicates that the procedure is optional.

#### 3.1.4 Will

Used only to indicate the future, not a degree of requirement.

#### 3.1.5 Can

Indicates a possibility or ability.

## 4 Safe use of oxy-fuel gas welding and cutting apparatus

The following DOs and DO NOTs can reduce the likelihood of a serious incident occurring. These lists are not intended to be comprehensive.

### 4.1 DOs for use of oxy-fuel gas welding and cutting apparatus

The following DOs apply to all oxy-fuel gas welding and cutting apparatus:

- Carefully read the equipment manufacturer's operating instructions before using any equipment. If the operator does not have the operating instructions, obtain a copy from the manufacturer or the local distributor. Additional information on equipment can be found in the publications listed in Section 7;
- Have a trained person demonstrate the proper procedures before attempting to set up or use the equipment unless the operator has already been trained;
- Follow the equipment manufacturer's operating instructions at all times. Deviation from these instructions can result in property damage, personal injury, and/or loss of life;
- Inspect oxygen regulators before installing them on cylinders. Inlet connections shall be clean. If there is evidence of oil, grease, or other contaminants on the nut, nipple, or filter, remove the regulator from service and have it inspected and cleaned by a qualified repair facility before using it;