



**CSA  
Group**

**S851-12**

# Post-blast safety evaluation of buildings



# Legal Notice

This document is provided by the Canadian Standards Association (operating as "CSA Group") as a convenience only.

## Disclaimer and exclusion of liability

This document is provided without any representations, warranties, or conditions of any kind, express or implied, including, without limitation, implied warranties or conditions concerning this document's fitness for a particular purpose or use, its merchantability, or its non-infringement of any third party's intellectual property rights. CSA Group does not warrant the accuracy, completeness, or currency of any of the information published in this document. CSA Group makes no representations or warranties regarding this document's compliance with any applicable statute, rule, or regulation.

IN NO EVENT SHALL CSA GROUP, ITS VOLUNTEERS, MEMBERS, SUBSIDIARIES, OR AFFILIATED COMPANIES, OR THEIR EMPLOYEES, DIRECTORS, OR OFFICERS, BE LIABLE FOR ANY DIRECT, INDIRECT, OR INCIDENTAL DAMAGES, INJURY, LOSS, COSTS, OR EXPENSES, HOWSOEVER CAUSED, INCLUDING BUT NOT LIMITED TO SPECIAL OR CONSEQUENTIAL DAMAGES, LOST REVENUE, BUSINESS INTERRUPTION, LOST OR DAMAGED DATA, OR ANY OTHER COMMERCIAL OR ECONOMIC LOSS, WHETHER BASED IN CONTRACT, TORT (INCLUDING NEGLIGENCE), OR ANY OTHER THEORY OF LIABILITY, ARISING OUT OF OR RESULTING FROM ACCESS TO OR POSSESSION OR USE OF THIS DOCUMENT, EVEN IF CSA GROUP HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES, INJURY, LOSS, COSTS, OR EXPENSES.

In publishing and making this document available, CSA Group is not undertaking to render professional or other services for or on behalf of any person or entity or to perform any duty owed by any person or entity to another person or entity. The information in this document is directed to those who have the appropriate degree of experience to use and apply its contents, and CSA Group accepts no responsibility whatsoever arising in any way from any and all use of or reliance on the information contained in this document.

## Intellectual property rights and ownership

As between CSA Group and the users of this document (whether it be in printed or electronic form), CSA Group is the owner, or the authorized licensee, of all works contained herein that are protected by copyright, all trade-marks (except as otherwise noted to the contrary), and all inventions and trade secrets that may be contained in this document, whether or not such inventions and trade secrets are protected by patents and applications for patents. Without limitation, the unauthorized use, modification, copying, or disclosure of this document may violate laws that protect CSA Group's and/or others' intellectual property and may give rise to a right in CSA Group and/or others to seek legal redress for such use, modification, copying, or disclosure. To the extent permitted by licence or by law, CSA Group reserves all intellectual property rights in this document.

## Patent rights

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. CSA Group shall not be held responsible for identifying any or all such patent rights. Users of this document are expressly advised that determination of the validity of any such patent rights is entirely their own responsibility.

## Use of this document

This document is being provided by CSA Group for informational and non-commercial use only. If you do not agree with any of the terms and conditions contained in this Legal Notice, you may not use this document. Use of this document constitutes your acceptance of the terms and conditions of this Legal Notice.



# ***Standards Update Service***

*S851-12*

*October 2012*

**Title:** *Post-blast safety evaluation of buildings*

**Pagination:** **67 pages** (vii preliminary and 60 text), each dated **October 2012**

To register for e-mail notification about any updates to this publication

- go to **shop.csa.ca**
- click on **CSA Update Service**

The **List ID** that you will need to register for updates to this publication is **2422093**.

If you require assistance, please e-mail [techsupport@csagroup.org](mailto:techsupport@csagroup.org) or call 416-747-2233.

Visit CSA Group's policy on privacy at [csagroup.org/legal](http://csagroup.org/legal) to find out how we protect your personal information.



*S851-12*  
***Post-blast safety evaluation of buildings***



*™A trade-mark of the Canadian Standards Association, operating as "CSA Group"*

*Published in October 2012 by CSA Group  
A not-for-profit private sector organization  
5060 Spectrum Way, Suite 100, Mississauga, Ontario, Canada L4W 5N6  
1-800-463-6727 • 416-747-4044*

***Visit our Online Store at [shop.csa.ca](http://shop.csa.ca)***



CSA Group prints its publications on Rolland Enviro100, which contains 100% recycled post-consumer fibre, is EcoLogo and Processed Chlorine Free certified, and was manufactured using biogas energy.

To purchase standards and related publications, visit our Online Store at [shop.csa.ca](http://shop.csa.ca) or call toll-free 1-800-463-6727 or 416-747-4044.

ISBN 978-1-77139-030-9

© 2012 CSA Group

All rights reserved. No part of this publication may be reproduced in any form whatsoever without the prior permission of the publisher.

# Contents

Task Force on Post-Blast Assessment of Buildings vi

Preface vii

## **0 Introduction 1**

0.1 General 1

0.2 Overview 1

0.3 Users 1

0.4 Classification and marking 1

## **1 Scope 1**

## **2 Reference publications 2**

## **3 Definitions and abbreviations 3**

3.1 Definitions 3

3.2 Abbreviations 4

## **4 Evaluation methodology 4**

4.1 Objective 4

4.2 Evaluation levels 5

4.2.1 General 5

4.2.2 Preliminary evaluation 5

4.2.3 Level I structural evaluation 5

4.2.4 Level II structural evaluation 6

4.2.5 Localized damage 6

4.3 Marking 6

## **5 General procedures for qualified inspectors and engineers 8**

5.1 Duties 8

5.1.1 Liaison with responders 8

5.1.2 Liaison with occupants and owners 8

5.2 Professional judgment 8

5.2.1 General 8

5.2.2 Training 8

5.3 Dangerous substances 8

## **6 Preliminary evaluation 9**

6.1 General 9

6.2 Qualified inspectors — Emergency management program 9

6.3 Documentation 9

6.3.1 Blast documentation 9

6.3.2 Evaluation forms 10

6.4 Preliminary evaluation safety classification 10

6.4.1 Classification 10

6.4.2 Criteria 10

6.5 Building evaluation 10

6.5.1 General 10

6.5.2 Adjacent building assessment 11

6.5.3 Limited access inspection 11

6.5.4 Evaluation 11

- 6.5.5 Internal explosions 11
- 6.5.6 Fire and high temperature 11
- 6.6 Hazard identification and marking 11
  - 6.6.1 General 11
  - 6.6.2 Geotechnical hazards 11
  - 6.6.3 Damaged architectural elements 11

## **7 Level I structural evaluation 15**

- 7.1 General 15
- 7.2 Qualified reviewers 15
- 7.3 Documentation 15
  - 7.3.1 Blast documentation 15
  - 7.3.2 Evaluation forms 15
- 7.4 Level I structural safety classification 15
  - 7.4.1 General 15
  - 7.4.2 "Level I safe" 15
  - 7.4.3 "Level I safety uncertain" 16
  - 7.4.4 "Level I unsafe" 16
- 7.5 Building evaluation 16
  - 7.5.1 General 16
  - 7.5.2 Exterior survey 16
  - 7.5.3 Interior survey 17
  - 7.5.4 Fire evaluation 17
- 7.6 Classification criteria for Level I structural evaluation 17
  - 7.6.1 General 17
  - 7.6.2 Construction types 17
  - 7.6.3 Reinforced concrete buildings 18
  - 7.6.4 Steel frame buildings 18
  - 7.6.5 Masonry buildings 18

## **8 Level II structural evaluation 24**

- 8.1 General 24
- 8.2 Qualified reviewers 24
- 8.3 Level II structural safety classification 25
  - 8.3.1 General 25
  - 8.3.2 "Level II safe" 25
  - 8.3.3 "Level II unsafe" 25
- 8.4 Building evaluation 25
  - 8.4.1 Engineering judgment 25
  - 8.4.2 Typical procedures 25
  - 8.4.3 Ductility of building structural system 25
- 8.5 Rehabilitation decisions 25

## **Annexes**

- A** — Commentary 44
- B** — Post-blast assessment forms 51
- C** — Building access markings 56

---

## **Tables**

- 1** — Preliminary evaluation criteria 14
- 2** — General classification criteria for Level I structural evaluation of buildings and danger areas 19
- 3** — Safety classification criteria for Level I structural evaluation of concrete buildings 20
- 4** — General safety classification criteria for Level I structural evaluation of steel frame buildings 22
- 5** — Safety classification criteria for Level I structural evaluation of masonry buildings 24

**Figures**

- 1** — Post-blast building evaluations and actions 7
- 2** — Collapse of ceiling and light fixtures — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Safety Uncertain” 26
- 3** — Collapse of ceiling and light fixtures — Preliminary Classification: “Level I Unsafe” — Level I Structural Classification: “Safety Uncertain” 27
- 4** — Shift of structural elements/building out of plumb — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Unsafe” 28
- 5** — Severe damage to primary structural elements — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Unsafe” 29
- 6** — Severe damage to primary structural elements — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Unsafe” 30
- 7** — Hazard due to falling debris — Preliminary Classification: “Unsafe” (danger zone only) 31
- 8** — Obstructed access due to a large crater — Preliminary Classification: “Unsafe” (danger zone only) — Level I Structural Classification: “Level I Safety Uncertain” 32
- 9** — Severe local damage — Preliminary Classification: “Unsafe” (danger zone only) — Level I Structural Classification: “Level I Safety Uncertain” 32
- 10** — Minor glazing damage — Preliminary Classification: “Safety Uncertain” — Level I Structural Classification: “Level I Safe” 33
- 11** — Extensive architectural and glazing damage — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Safety Uncertain” 34
- 12** — Global damage and architectural/glazing damage — Preliminary Classification: “Unsafe” — Level I Structural Classifications: “Level I Unsafe” and “Level I Safety Uncertain” 35
- 13** — Global damage — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I unsafe” 36
- 14** — Global damage — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Unsafe” 37
- 15** — Localized damage — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Unsafe” 38
- 16** — Localized damage — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Unsafe” 39
- 17** — Column failure — Preliminary Classification: “Safety Uncertain”— Level I Structural Classification: “Level I Unsafe” 40
- 18** — Column failure — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Unsafe” 41
- 19** — Column failure — Preliminary Classification: “Unsafe” — Level I Structural Classification: “Level I Unsafe” 42
- 20** — Connection failure — Preliminary Classification: “Safety Uncertain” — Level I Structural Classification: “Level I Unsafe” 43
- 21** — Failure of unreinforced masonry walls — Preliminary Classification: “Unsafe”— Level I Structural Classification: “Level I Unsafe” 43

# ***Task Force on Post-Blast Assessment of Buildings***

<b>A.G. Razaqpur</b>	McMaster University, Hamilton, Ontario	<i>Chair</i>
<b>J. Buck</b>	City of Ottawa, Ottawa, Ontario	
<b>K. Clupp</b>	Royal Canadian Mounted Police, Ottawa, Ontario	
<b>S.H. Foo</b>	Public Works & Government Services Canada, Gatineau, Québec	
<b>M. Gareau</b>	Service de sécurité incendie de Montréal, Montréal, Québec	
<b>A. Malhotra</b>	Halsall Associates Ltd., Ottawa, Ontario	
<b>C. May</b>	Public Safety Unit for the Toronto Police Service, Toronto, Ontario	
<b>P. Pagotto</b>	Public Safety Canada, Ottawa, Ontario	
<b>T. Stewart</b>	Department of Foreign Affairs and International Trade, Ottawa, Ontario	
<b>J-Y. Vermette</b>	Canadian Bomb Data Centre, Ottawa, Ontario	
<b>D. Wilson</b>	The City of Calgary Fire Department, Calgary, Alberta	
<b>D. Torrey</b>	CSA Group, Mississauga, Ontario	<i>Project Manager</i>

# Preface

This is the first edition of CSA S851, *Post-blast safety evaluation of buildings*.

In addition to the subject building, a large-size blast event in a city environment can cause damage to a large number of buildings. To ensure the safety of the occupants of buildings affected by a blast event, and to minimize the potential economic losses caused by the closure or disruption of the normal operation of the affected buildings, it is necessary to evaluate these buildings for their safety and serviceability before they can be reoccupied. Depending on the number and size of buildings involved, and given the desire to minimize unnecessary disruptions in the lives of the occupants and to essential services, it is necessary to develop systematic procedures for post-blast safety evaluation of buildings.

This Guideline was developed based on the “Guide for post-blast safety evaluation of buildings” (Razaqpur et al. 2011). This Guideline applies to suspected or known blast incidents and provides recommendations for emergency response authorities to develop suitable standard operating procedures incorporating criteria for post-blast safety inspection and assessment.

Although this Guideline is intended to be comprehensive, specific agencies might need to refine procedures as appropriate for their own usage.

CSA Group gratefully acknowledges McMaster University for the development of post-blast evaluation procedures, and financial support from Defence Research and Development Canada, Centre for Security Science, through project CRTI 3780-2011-30xa-12.

This Guideline was prepared by the Task Force on Post-Blast Assessment of Buildings.

## Notes:

- (1) Use of the singular does not exclude the plural (and vice versa) when the sense allows.
- (2) Although the intended primary application of this Guideline is stated in its Scope, it is important to note that it remains the responsibility of the users of the Guideline to judge its suitability for their particular purpose.
- (3) To submit a proposal for change, please send the following information to [inquiries@csagroup.org](mailto:inquiries@csagroup.org) and include “Proposal for change” in the subject line:
  - (a) designation (number);
  - (b) relevant clause, table, and/or figure number;
  - (c) wording of the proposed change; and
  - (d) rationale for the change.



# S851-12

## ***Post-blast safety evaluation of buildings***

### **0 Introduction**

#### **0.1 General**

This Guideline is intended to provide systematic procedures for post-blast structural safety evaluation of buildings. It presents the basic elements necessary to achieve expedient and safe evaluation of buildings affected by a blast event. It provides guidance to the authority having jurisdiction (AHJ) to develop suitable standard operating procedures incorporating criteria for post-blast safety inspection and assessment.

**Notes:**

- (1) *Although emphasis is placed on malicious explosions, these procedures may be equally applied to accidental blast events.*
- (2) *Post-blast hazards not addressed in this Guideline include but are not limited to air quality, damaged mechanical and electrical equipment, debris, fire, hazardous materials (i.e., CBRN), secondary explosives, gas leaks, and flooding. See [Clause A.0.1](#) for information on additional precautions, including personal protective equipment (PPE).*

#### **0.2 Overview**

The objective of this Guideline is to provide an engineering basis for assessment of the safety of the structural and architectural components of a building after a blast event. Preliminary, Level I structural, and Level II structural evaluation procedures are used to classify the safety of a building.

Structural assessment is one component of the assessment of a building after a post-blast event. The various types of necessary evaluation are identified in [Clause 4](#).

Although the procedures in this Guideline are presented in a format that applies to a single building, the principles can be applied to multiple buildings.

#### **0.3 Users**

This Guideline is intended as a tool for qualified inspectors, engineers, and urban search and rescue (USAR) personnel. It provides guidance to an AHJ to develop suitable standard operating procedures (SOP) for performing post-blast safety inspection and assessment. Although the Guideline is comprehensive, further refinement might be necessary by the AHJ as appropriate for implementation.

#### **0.4 Classification and marking**

This Guideline has been developed to assist in the proper classification of post-blast safety of buildings. Although typical methods of marking have been provided in [Annex C](#), requirements for marking are outside of the scope of this Guideline.

### **1 Scope**

#### **1.1**

This Guideline specifies procedures for the assessment of the safety of the structural and architectural components of a building affected by a blast event.